

Industrial Adaptor Plate Kit

FIXINGS TO MOUNT TO OLD-STYLE GRIFCO AND ATA AXESS 2000 PLATES

ADAPTOR PLATE KIT - SAP# ORDER NO. 62623		
ITEM	DESCRIPTION	QTY
1	ADAPTOR PLATE	1
2	HEX SERRATION FLANGE NUT M12	4
3	SPRING WASHER ID12	8
4	FLAT WASHER M12	8
5	M12X40 HEX HEAD BOLT	4
6	FLAT COUNTERSUNK HEAD SCREW M12X35	4

Installation Instruction

1. Insert 4 x M12x35 Countersunk screws (6) through the adaptor plate (1) and into the mounting holes of the gearbox flange.
2. To connect the adaptor plate (1) to the Grifco / Axess plate, insert 4 x M12x40 Hex Head Bolts (5) through spring washers (3) and flat washers (4) as shown and secure on the other side of the adaptor plate (1) with 4 x flat washer (4), spring washer (3) and M12 Hex Flange nuts (2).

